

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 09

Township: 8 North

Range: 2 West

Corner ID: Van Bu I-05


Monument Description & Remarks: Found 1½" bent Iron Pipe, 12" under surface of black top, at NW corner of section. (Witness measurements to center of pipe, 3" below top.)

References On File: Survey drawing of Wilson Minor Subdivision by Graham Surveying, on file in the County Surveyor's Office.

RECOVERY TIE DRAWING

Field Book 99-01 Page No. 45

USGS Whitc hall Quad



A - 1½" Iron Pipe

B - North 15° West, 17.10' from pipe
MAG nail in 7" Shagbark Hickory

Survey marker sign set 4' up


C - South 11° West, 27.14' from pipe
MAG nail in 26" Sassafras

D - North 79° West, 71.60' from pipe
MAG nail in 9" powerline pole

Not To Scale

Compass Bearing Magnetic North

I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of Section 36-2-12-11 of the Indiana Code; and the above data is given under my hand and seal this 4th day of August, 1999.



Administered by the Monroe County Surveyor Review Board

Date: November 18, 1999